


CLEANING AGENT SELECTING CHART

◎: Recommendable ○: Applicable

Product		CLEANING TARGET							WORK PIECE MATERIAL						DILUTION RATIO		
		ADFIX	SKYWAX	SHIFTWAX	ALCOWAX	ALCOWAX	PLAINCOAT	MINERAL OIL	PARTICLE	SILICON WAFER	POLISHING PLATE	NEODYMIUM MAGNET	ALUMINIUM, COPPER	CERAMICS 		QUARTZ	
ALKALINE DETERGENT	DEVEL	◎	*1	◎		◎	*2				◎	○		◎		5 ~ 10% (x 10 ~ 20)	
	DEVEL-A	◎		◎		◎					◎	○		○			5% (x 20)
	RUNGEL F	○							○					◎	◎		5 ~ 10% (x 10 ~ 20)
	NORMAL A	○						◎	○	◎					◎		10% (x 10)
	CLAIR C	○							○	◎					◎		10% (x 10)
	PLETOLE							◎				◎					3.3 ~ 10% (x 10 ~ 30)
HIGH PURITY ALKALINE DETERGENT	KILALACLEAN 101	○		◎		◎			◎	○			○		3.3 ~ 10% (x 10 ~ 30)		
	KILALACLEAN 301					◎			◎						3.3% (x 30)		
SEMI-AQUEOUS SOLVENT	NIKKASOLE SW			○	○						○	◎	◎	○	Undiluted		
SOLVENT	NIKKASOLE AC-100	○									○	◎	◎	○	Undiluted		
	NIKKASOLE RE		◎	◎	◎	◎	○				○	◎	◎	○	Undiluted		
	NIKKASOLE LC		◎	◎	◎	◎	◎								Undiluted		
NEUTRAL	PLACLEAN HNC						○	◎				◎	◎		2% (x 50)		
DE-GREASE	EMUNIKKA #2		*1				◎					◎	◎		0.75 ~ 1% (x 100 ~ 150)		
	EMUNIKKA #55	○				○	◎						◎		10% (x 10)		
METALIC ION REMOVER	FERRITOL												◎	◎	2% (x 50)		
CONDITIONER	DRYNON C							◎	◎	◎				◎	2 ~ 10% (x 10 ~ 50)		

*1: DEVEL can de-wax some types of SKYWAX.

*2: Consult us for cleaning agent of PLAINCOAT.

*3: Not including Ceramics which does not have alkali-resistant ability.

Please refer to SDS of each product for appropriate application and handling before use.